- Site Service Report -

Date:January 10, 2012

IRD SO.: 11167

To: Cindy Mantie

From: Steven Schroeder

Project Name/Location: PA LTPP **Service Date(s):** 4-20-2011

Job Description: Perform Scheduled Maintenance.

Work Completed: 4-20-11 Performed electrical check. All sensors tested ok.

6/19/96 IRD FORM No.: <u>1304A</u>

Notes:

Date: Job #:	4/20/2011 11167	Kistler State: Pa Site #: 158		Location: Directions:		System Type: Milesburg,PA I-80 mm 158		iSinc	
		WBDr1	WBDr2						
Loops	Lane -	4							
Resistance		1.2	1.3						
Leakage									
Shield		ol	ol						
Inductance(uh)		145.0	152.0						
Vietlene	Γ.	164	1/0	1/0	17.4				
Kistlers	Lane -	K1	K2	K3	K4			1	Ī
Amplitude	co(nf)	15.6	15.4	11.3	15.0				
Capacitance(nf) Resistance		ol	ol	ol	23M				
Piezos Amplitude Capacitano Resistance									
<u>System</u>				Temp S	<u>ensor</u>				
A/C Service			White+						
Power Supply				Re	ed +				
Solar Pane	el								
Back-Up		13.3 Software							
System Input		System							
Modem Power			Loop						
Phone off				Pi	ezo				
Phone on									
Site Full Capacity	Operating			Pass X					

Fail



INTERNATIONAL ROAD DYNAMICS INC.

702 - 43rd Street East, Saskatoon, SK, Canada, Phone: (306) 653-6600 Fax: (306) 242-5599

Technician: Steven Schroeder Date: 4/20/11

Action Items:

Item	Action Required	Ownership
1.		
2.		
3.		
4.		